

*Fig. 1*




Fig.2




Fig. 3B




Fig. 3A




Fig. 4C




Fig. 4B




Fig. 4A





Fig.5




*Fig. 6*

		R	G	B	Y	Cb	Cr
MARKER COLOR.	RED	255	173	230	186.166	14.66077	54.98532
	BLUE	83	246	255	192.479	32.00379	-61.5791
	YELLOW	234	254	158	220.696	-44.6275	10.57143
	GREEN	169	255	143	204.688	-41.4901	-22.3473

*Fig. 7*

TILE	ANALYSIS RESULT
T0	
T1	
T2	
T3	RED
⋮	
⋮	
⋮	
⋮	
⋮	
T100	
T101	YELLOW
T102	YELLOW
T103	YELLOW
⋮	
⋮	
⋮	
⋮	
⋮	
T200	BLUE
T201	BLUE
T202	BLUE
T203	
⋮	
⋮	
⋮	
⋮	
⋮	

Fig. 8



*Fig. 9*

MARKER COLOR	DESTINATION	REPLACEMENT COLOR
RED	A	RED(0)
YELLOW	B	BLACK(1)
BLUE	C	BLUE(2)

*Fig. 10*






Fig. 11




Fig. 12A




Fig. 12B




Fig. 13A

80A


81	AAA	XXXXXXXXXXXXXXXXXXXX
	BBB	XXXXXXXXXXXXXXXXXXXX
	CCC	XXXXXXXXXXXXXXXXXXXX
72	ABC	XXXXXXXXXXXXXXXXXXXX
	BCA	XXXXXXXXXXXXXXXXXXXX
	CAB	XXXXXXXXXXXXXXXXXXXX
	XYZ	XXXXXXXXXXXXXXXXXXXX
	YZX	XXXXXXXXXXXXXXXXXXXX
	ZXY	XXXXXXXXXXXXXXXXXXXX
83	LMN	XXXXXXXXXXXXXXXXXXXX
	MLN	XXXXXXXXXXXXXXXXXXXX
	NLM	XXXXXXXXXXXXXXXXXXXX



Fig. 13B

80B

71	AAA	XXXXXXXXXXXXXXXXXXXX
	BBB	XXXXXXXXXXXXXXXXXXXX
	CCC	XXXXXXXXXXXXXXXXXXXX
82	ABC	XXXXXXXXXXXXXXXXXXXX
	BCA	XXXXXXXXXXXXXXXXXXXX
	CAB	XXXXXXXXXXXXXXXXXXXX
	XYZ	XXXXXXXXXXXXXXXXXXXX
	YZX	XXXXXXXXXXXXXXXXXXXX
	ZXY	XXXXXXXXXXXXXXXXXXXX
83	LMN	XXXXXXXXXXXXXXXXXXXX
	MLN	XXXXXXXXXXXXXXXXXXXX
	NLM	XXXXXXXXXXXXXXXXXXXX

Fig. 14







*Fig. 16*

MARKER COLOR	DESTINATION
RED	A
YELLOW	B
BLUE	C

*Fig. 17*



*Fig. 18*



*Fig. 19*

MARKER COLOR	DESTINATION	CUTOFF LEVEL
RED	A	0
YELLOW	A	1
YELLOW	B	0
BLUE	B	2